

The Devil is in the Detail















The Baltimore Bridge collapse was a cyber attack and they know it. Their own intel agencies told them from the start and yet they are still denying it. Oh well. There is only one truth & nothing any of us say can change it.

6:44 PM · Mar 31, 2024 · **355.7K** Views





@CharlesleeTX1911 @Charles07788205 · Mar 31

Commercial cargo ships like the Dali cannot be remotely hacked. They could only be hacked by someone onboard using a zip drive to insert malicious code.

Their computer systems simply don't have the downlink capability necessary.

Was MV Dali hacked?

Almost certainly not.


Can ships be hacked?

Yes.


















Blackout

Loss of electrical power leading to loss of propulsion and steering








Ideal Recovery


Generator trips - blackout Emergency generator starts Standby generator starts Ancillaries start Main engine can be used













































MV Dali Recovery

Transformer trips – blackout 1 Emergency generator starts Transformer manually restored Both generators trip – blackout 2 Standby generator starts Ancillaries start Main engine can be used








THE SWISS CHEESE RESPIRATORY VIRUS PANDEMIC DEFENCE

RECOGNISING THAT NO SINGLE INTERVENTION IS PERFECT AT PREVENTING SPREAD



PERSONAL RESPONSIBILITIES

SHARED RESPONSIBILITIES

EACH INTERVENTION (LAYER) HAS IMPERFECTIONS (HOLES). MULTIPLE LAYERS IMPROVE SUCCESS.


UPDATE: 240CT2020
















Integrated Control and Monitoring System

















Unassigned wall-ports need 802.1x

Or you go into the tar pit!


































Published March 2024

REPORT MARINE 2024/05

Loss of propulsion and near grounding of Viking Sky, Hustadvika, Norway 23 March 2019






Figure 15: Events during restoration of power. Source: The Norwegian Coastal Administration AIS / NSIA






Figure 30: Schematic drawing of the diesel generator lubricating oil system. Illustration: NSIA

nTestPartnersLLP








Figure 30: Schematic drawing of the diesel generator lubricating oil system. Illustration: NSIA


nTestPartnersLLP






















The following operator inputs were required for remote monitoring of the sump tanks:


- Offset of the sensor tube (mm)
- Density of the oil (g/cm3)
- Alarm levels (m3)


These values could be adjusted in the IAS by any of the engineers, with **no means of identifying what had been changed, by whom, when or why**.















The installation of the sensor system in the lube oil sump tank is shown. In addition to the external air supply, the module requires input from **two barometric reference sensors** for measurement correction.

There were approximately 150 audible alarms in total. 88 were tank level warnings that returned to normal condition within 2 minutes. These warnings were likely caused by a short term pressure fluctuation at one of the barometric reference sensors.






It was identified that the aft draft sensor was sending erroneous readings to NAPA. This was affecting the level correction done by NAPA and thus also led to wrong volume calculations.





The investigation has identified that there was an error in the 3D model geometry. This caused an error in the calculations.

The volume calculation will return a value 568 litres less than the actual oil volume.







The remote tank level monitoring system was complex, and the measurements were inaccurate and unreliable. The crew had gradually lost confidence in the remote monitoring system.

The investigation has found that the fleet of Viking cruise vessels was operated for years without the crew or shoreside personnel knowing the correct lube oil sump tank filling levels or alarm setpoints.





Unable to determine lube oil levels

Didn't know what lube oil levels should be...





Inputs: NAPA software 3D tank models Barometric pressure Offset Oil density Heel and trim








Can the crew of a modern vessel possibly understand exactly how these systems work?


















· (O) ·
















```
csvload.scr - Notepad

File Edit Format View Help

open scp://CS5000: 192.168.200.161/ -hostkey=*
get -latest /mnt/sd/modbus-tcpip/*.csv ccp.csv
exit
```


```
CS5000@192.168.1.4's password:
$ whoami
CS5000
$ cat /etc/shadow
root:$
                                        1:10933:0:99999:7:::
bin:*:10933:0:99999:7:::
daemon: *: 10933:0: 99999:7:::
adm: *:10933:0:99999:7:::
lp:*:10933:0:99999:7:::
sync:*:10933:0:99999:7:::
shutdown: *:10933:0:99999:7:::
halt:*:10933:0:99999:7:::
uucp:*:10933:0:99999:7:::
backup:$
                                         1.:10933:0:99999:7:::
operator:*:10933:0:99999:7:::
nobody: *:10933:0:99999:7:::
vdradmin
                                            /:10933:0:999999:7:::
CS5000:$
                                            10965:0:99999:7:::
```


Many systems are redundant to hardware failure, power loss, even fire and flooding – but not cyber-attack.


















Voyage Data Recorder











artnersLLP



info@pentestpartners.com

PenTestPartnersLLP








IP	At MAC Address	Count	Len	MAC Vendor / Hostname
10.0.6.1	9c:dc:71:c1:59:9b	13	780	Hewlett Packard Enterprise
10.0.0.2	00:d0:1d:06:63:03	1	60	FURUNO ELECTRIC CO., LTD.
10.0.0.100	00:e0:27:26:0b:31	1	60	DUX, INC.
10.0.0.101	90:2e:16:d1:c3:d6	1	60	LCFC(HeFei) Electronics Technology co., ltd
10.0.0.120	00:d0:1d:11:98:62	2	120	FURUNO ELECTRIC CO., LTD.
10.0.0.130	00:d0:1d:11:98:f3	1	60	FURUNO ELECTRIC CO., LTD.
10.0.0.140	00:02:9f:04:95:3c	1	60	L-3 Communication Aviation Recorders
10.0.0.150	00:06:cb:1b:01:d0	1	60	Jotron Electronics A/S
10.0.6.23	00:15:5d:e1:c3:04	3	180	Microsoft Corporation










```
public static String decryptoString(byte[] bArr) {
    LOGGER.debug("##### Call VDR_AES_Decrypt #####");
    if (linkedDLL) {
        return VDR_AES_Decrypt(bArr);
    }
    LOGGER.fatal("Can't call native method.");
    return null;
}
```

```
[net.FileTransporter:retrieveFile:L?] - Get [/opt/vr/data/onIndb/config/configuril.VDRSecurityJNI:decryptoString:L?] - ##### Call VDR_AES_Decrypt #####
[util.VDRSecurityJNI:decryptoString:L?] - ##### Call VDR_AES_Decrypt #####
[net.FileTransporter:createDestinationClient:L?] - Host name : 10.0.0.100
[net.FileTransporter:createDestinationClient:L?] - Login name : ftp-reader
[net.FileTransporter:createDestinationClient:L?] - Passward :
[net.FileTransporter:createDestinationClient:L?] - Timeout : 180000
```







A broken VDR doesn't have immediate safety impact...


But it can stop you sailing due to regulatory reasons...




















Transmit only works!













Modbus – request/reply Needs transmit/receive






















Azipods







"The azipods are connected to the ICMS by serial and for monitoring only"






Discrete Serial








Discrete Serial





















































But you are still on the ship?
























```
18:12 +00:21.064 🔊 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Reply) { 250 1223 1175 1197 ... }
 :08:13 +00:22.064 ← 0000 01 03 00 64 00 03 44 14
7:08:13 +00:22.064 🙋 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Request) Addr: 0x0064 N: 3
 :08:14 +00:22.150 → 0000 01 03 06 00 00 01 A4 00 00 61 6A
7:08:14 +00:22.150 🔊 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Reply) { 0 420 0 }
7:08:15 +00:23.172 ← 0000 01 03 00 68 00 4B 84 21
7:08:15 +00:23.172 🙋 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Request) Addr: 0x0068 N:
 :08:15 +00:23.210 → 0000 01 03 96 01 40 00 46 01 70 01 06 01 11 00 3F 00 ....@.F.|....?.
7:08:15 +00:23.306 → 0010 FC 00 F1 01 1A 02 1F 01 E2 02 1B 02 0C 02 07 01 ...........
                → 0020 E9 02 0F 02 19 01 D5 01 DE 01 99 01 AB 01 9F 00 0....0.0.....
                 → 0030 FF 00 E9 00 F7 02 A8 02 BB 02 A8 02 92 02 A8 02 ...........
                 → 0050 C5 02 CF 02 CF 02 CF 02 D9 02 D9 01 17 01 17 01 }.c.c.c.0.0.....
                 → 0060 17 02 A8 02 A8 02 A8 02 B2 02 A8 02 A8 02 A8 02 .....
→ 0080 B8 0E 91 0E C2 0E 72 12 51 12 2A 0F A9 0B 40 01 .....r.Q.*...@.
                 → 0090 46 01 48 01 44 00 00 FF FE 02 0C
7:08:15 +00:23.420 🔊 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Reply) { 320 70 380 262 ...]
7:08:16 +00:24.421 ← 0000 01 03 00 00 00 64 44 21
7:08:16 +00:24.421 🗞 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Request) Addr: 0x0000 N: 100
7:08:16 +00:24.551 → 0000 01 03 C8 00 FA 04 C7 04 97 04 AD 02 44 01 3A 01 ..Ä...Ñ.....D.:.
                → 0010 C5 00 00 00 00 00 00 FF FF 00 00 00 1E 00 00 01 1......
                 → 0020 44 00 B4 01 46 01 48 01 44 01 00 04 2C 00 2B 00 D...F.H.D...,.+.
                 → 0040 FE 00 2B 01 06 01 02 01 07 01 B9 01 BD 01 BD 01 ..+....
7:08:16 +00:24.665 → 0050 BF 01 BD 01 BB 01 C5 01 BA 01 AC 01 BF 01 BB 01 .....Ł......
                 → 0060 BE 00 96 00 7E 00 8F 01 EA 01 15 01 16 01 18 03 ....~...□......
                 → 0070 7B 03 73 03 76 03 74 03 79 03 80 03 77 03 7B 03 {.s.v.t.y...w.{.
                 → 0080 7B 03 67 03 77 01 76 01 76 00 F9 00 8C 00 8C 02 {.g.w.v.v.....
                 → 0090 62 02 E4 01 40 01 68 00 8C 00 8C 02 80 03 20 01 b. 0...h.......
                 → 00A0 36 01 C2 00 96 00 BE 02 44 02 E4 01 4A 01 4A 01 6......D.D......
                 → 0080 04 00 C8 02 F8 03 0C 01 4A 01 5E 01 47 01 49 01 ..Â....J.^.G.I.
7:08:16 +00:24.764 > 00C0 44 01 57 0B 09 00 00 00 00 01 7C AF 3F
                                                                  :08:16 +00:24.764 🔊 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Reply) { 250 1223 1175 1197 ...
 :08:17 +00:25.765 ← 0000 01 03 00 64 00 03 44 14
7:08:17 +00:25.765 🙋 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Request) Addr: 0x0064 N: 3
 :08:17 +00:25.838 > 0000 01 03 06 00 00 01 A4 00 00 61 6A
 :08:17 +00:25.838 🔊 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Reply) { 0 420 0 }
7:08:18 +00:26.838 ← 0000 01 03 00 68 00 4B 84 21
7:08:18 +00:26.838 🚷 [+] MODBUS-RTU Dev: 1 Fn: 3 Read Holding Registers (Request) Addr: 0x0068 N: 75
 :08:18 +00:26.913 → 0000 01 03 96 01 40 00 46 01 7C 01 06 01 11 00 3F 00 ....@.F.|....?.
```
















Physical medium Protocol Data carried Dependencies between systems





"Aligning the holes" by stopping systems working can have massive impact.





Increased crew workload can have devastating effects under the wrong conditions.





It is becoming impossible for crew to understand exactly how all systems work.





Understanding the data flows and dependencies between systems is vital for security.





Thanks!

Any questions?

Twitter: @cybergibbons



